##531 - 1 **5**13 - 15

TERRETER TO

	:		to the company of the com-		
		s enegana			1
25X1A	y na troit				and the second s
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	:			TRYORILY
	1	:			
	:	TOP: 06462 17 NOV 65			IN: 72171 25X1A
	911 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	to the decision of the second	Section 1995 Annual Control of the Section 1995 Ann	The state of the s	- 13 
				<del></del>	
	16				
				2	
		THAT THE AUTO-PILOT CAN BE OVERPOWERED WITH RELATIVE EASE, OR DISENGAGED IN A FEW SECONDS. HOWEVER. THE CAPABILITY OF THE PILOT TO EFFECT TIMELY CORRECTIVE ACTION IS A DIRECT			
		FUNCTION OF THE PILOTS ATT	entiveness at th	E INSTANT THE	UPSET
		FROM PLANNED FLIGHT CONDIT	ION OCCURS. IN	ACCIDE	WT 25X1A
		THERE IS CONSIDERABLE EVID	ENCE TO SUPPORT	THE PROPOSITI	ON THAT
	8	HE WAS INVOLVED IN "COCKPIT BOOK KEEPING" AT THE TIME OF			
		INITIAL INDICATION OF TROUBLE.			
		2. WITH HQS CONCURRENC	E I PLAN TO STOP	BY ON	22 NOV 25X1A
		TO DISCUSS RECOMMENDATIONS	IN DETAIL WITH [	AND	WOULD 25X1A
		APPRECIATE THE OPPORTUNITY	TO DISCUSS BOAR	D FINDINGS WI	TH
25X1A	. [	AT THAT TIME. T	OPSECRE	The second of th	END OF MSG
			THE ISSUED OF 10TH	li. S <b>ibulibu</b> ni a	© 34° ( <b>4</b> ° √